

Dominion KSX440, KSX 880 Local Port Physical Location Changes

Release Date: February, 2005

Last Updated: February, 2005

Location Changes of Local Admin and Local Access Console Ports

This change is reflected in the updated User Manual and Quick Setup Guide. The locations of the Local and the Admin ports depend on the KSX model. Dominion KSX units have a label on the underside of the chassis identifying the hardware version. The ID label will also be on the outer carton. The models that read either: Chassis RX440-F/S-0B or -0D or Chassis RX880-F/S-0B or -0D have the Local Admin ports on the rear panel and Local Access Console ports on the front panel (behind the bezel).

For those models with labels that read Chassis RX440-F/S-0F or Chassis RX880-F/S-0F; these locations are reversed: the Local Admin ports are found on the front panel (behind the bezel) and Local Access Console ports are on the rear panel.

Please consult the labeling on your Dominion KSX unit to determine where the Local and Admin ports are located. Functionality of either port has not changed.

Raritan Computer Inc.
400 Cottontail Lane
Somerset, NJ 08873
USA
Tel. 1-732-764-8886
Fax. 1-732-764-8887
E-mail: sales@raritan.com
<http://www.raritan.com>

Raritan Computer Europe, B.V.
Eglantierbaan 16
2908 LV Capelle aan den IJssel
The Netherlands
Tel. 31-10-284-4053
Fax. 31-10-284-4049
E-mail: sales.europe@raritan.com
<http://www.raritan.com>

Raritan Computer Japan, Inc.
[4th Flr. Shinkawa NS Building](#)
[1-26-2 Shin-kawa, Chuo-ku](#)
[Tokyo 104-0033](#) Japan
Tel. 81-03-3523-5991
Fax. 81-03-3523-5992
E-mail: sales@raritan.co.jp
<http://www.raritan.co.jp>

Raritan Computer Taiwan, Inc.
5F, 121, Lane 235,
Pao-Chiao Rd., Hsin Tien
Taipei Hsien, Taiwan, ROC
Tel. 886-2-8919-1333
Fax. 886-2-8919-1338
E-mail: sales.asia@raritan.com
<http://www.raritan.com.tw>